

• Tool Material :

most common { → high speed steel. → tungsten Carbide → higher speeds
→ longer life → higher hardness → lower cost

⇒ PCD : poly-crystalline diamond.

→ long life
→ expensive
→ only tip (cutting edge)

⇒ Ceramic : → no cooling
→ sparks

⇒ CBN : boron nitrate

⇒ TCT : tungsten carbide tipped

→ HST body
→ braised carbide tip

- Drills:
 - axial cutting
 - two cutting edges

- - - - -
↓
cutting diameter

- - - - -
↓
Shank diameter


- tools can be coated

- End Mill:
 - flat → ball
 - square → tapered
 - V → form tool
 - bull nose


(usually carbide)

for CNC
machines


→ axial + radial cutting
→ must be
center cutting




Number of flutes



Up Milling (conventional)



Down Milling (climb)



- for thin walls
- for foam
- needs less clamping pressure

- needs higher clamping pressure

→ spindle always turns clockwise ←

CNC Routing VS CNC Milling -

- Routing is milling
- Routing is only wood

-
- 1) calculate spindle speed (n)
 - 2) calculate feed speed (v_f)

FS Wizard . com

- usually depth of cut is 50% to 100% of tool diameter.

- usually width of cut is 60% to 70% of tool diameter.

- tabs \rightarrow 6-8 mm for 18mm plywood.

• Safety :

→ eye protection

→ no accessories

→ No over size or dangling clothes.

→ closed footwear.