

# Mastercam 2024 Resolved Issues

February 2023



# Mastercam 2024 Resolved Issues

February 2023

© 2023 CNC Software, LLC - All rights reserved.

Software: Mastercam 2024

## Terms of Use

Use of this document is subject to the Mastercam End User License Agreement. The Mastercam End User License Agreement can be found at:

<https://www.mastercam.com/legal/>

## Be sure you have the latest information!

Information might have changed or been added since this document was published. The latest version of the document is installed with Mastercam or can be obtained from your local Reseller. The Resolved Issues website—installed with each release—includes the latest information about Mastercam features and enhancements.

# Introduction

Please review this Resolved Issues for last-minute product information about Mastercam 2024. Report any problems to [qc@mastercam.com](mailto:qc@mastercam.com).



# Resolved Issues

The table below lists issues addressed in Mastercam 2024 and its updates.

Number	Release	Category	Description	Date
R-33090	PB1	<i>Milling Toolpaths</i>	Implement the fix for the Project Curves calculation change.	2/13/23
R-33313 R-33043	PB1	<i>Milling Toolpaths</i>	Unified Toolpath fails to generate and then shows an error.	2/13/23
R-31532	PB1	<i>Backplot/Verify/Simulation</i>	When you replace the Lathe machine from the Machine Group dialog, the change does not persist.	2/13/23
R-33381	PB1	<i>File Management</i>	When you import the attached SAT file, with the <b>Create hole operations</b> option on, the solid geometry and the associated points go to different levels.	2/13/23
R-31560	PB1	<i>Milling Toolpaths</i>	Area Roughing gives a computation error.	2/13/23
R-31892	PB1	<i>Milling Toolpaths</i>	The 2D Contour operation with remachining and multi passes gives an incorrect cut order.	2/13/23
R-32971	PB1	<i>CAD</i>	The <b>Transform to plane</b> result is different between Mastercam 2022 and 2023 when you select planes.	2/13/23
R-27122	PB1	<i>Milling Toolpaths</i>	Area Roughing gouges a boss.	2/13/23
D-50764	PB1	<i>CAD</i>	The bounding box cylinder does not cover the entire surface.	2/13/23
R-28843	PB1	<i>Milling Toolpaths</i>	The Waterline toolpath's cut order is incorrect when corner rounding and optimize are selected.	2/13/23
R-27567	PB1	<i>Milling Toolpaths</i>	The Waterline toolpath's cut order is incorrect when critical depths and optimize are selected.	2/13/23
R-31414	PB1	<i>Milling Toolpaths</i>	Dynamic OptiRough crashes when Mastercam generates the toolpath.	2/13/22
D-51119	PB1	<i>Backplot/Verify/Simulation</i>	Analyze Toolpath displays tip compensation incorrectly.	2/13/23
R-31369	PB1	<i>MP Post Processors</i>	MPFAN disrespects some values of ABS subprograms when contour endpoints match.	2/13/23
R-32799	PB1	<i>Milling Toolpaths</i>	Waterline rest passes generate the wrong cutting order.	2/13/23
R-32344	PB1	<i>Milling Toolpaths</i>	When you save a file, a toolpath with an approximate start point becomes dirty.	2/13/23
R-24993	PB1	<i>Milling Toolpaths</i>	The Contour <b>Profile Ramp, Lead In/Out</b> option is incorrect when you apply overlap.	2/13/23
R-31961	PB1	<i>Milling Toolpaths</i>	For any toolpath, the undo function creates an index	2/13/23

Number	Release	Category	Description	Date
			turret position and removes tool information from the toolpath.	
R-03166	PB1	<i>Milling Toolpaths</i>	First pass feed reduction does not work in Dynamic Contour.	2/13/23
S-101374	PB1	<i>File Management</i>	Improve level naming when you import solids from assembly files.	2/13/23
D-03228	PB1	<i>Milling Toolpaths</i>	2D Contour with <b>Multi passes</b> and <b>Keep tool down</b> retracts the tool.	2/13/23
R-32728	PB1	<i>Backplot/Verify/Simulation</i>	A Mill-Turn part causes Mastercam to crash during Verify.	2/13/23
R-03923	PB1	<i>Milling Toolpaths</i>	Waterline performs on/off moves at several positions around the part.	2/13/23
R-33534 R-33033	PB1	<i>Milling Toolpaths</i>	3D high speed toolpaths handle negative <b>Stock to leave</b> incorrectly.	2/13/23
R-32409	PB1	<i>Milling Toolpaths</i>	<b>Toolpath Transform</b> with five instances machines one instance differently and plunges into the material.	2/13/23
R-29863	TP4	<i>Milling Toolpaths</i>	Modifications to the <b>Cut tolerance</b> in a Blend toolpath affects <b>Entry</b> and <b>Exit</b> move output.	12/30/22
R-32400	TP4	<i>Milling Toolpaths</i>	The default feed rate is incorrect in the Model Chamfer toolpath.	12/30/22
R-31737	TP4	<i>Milling Toolpaths</i>	Using a start point in a duplicated Waterline operation effects the source operation.	12/30/22
R-31523	TP4	<i>Milling Toolpaths</i>	The <b>Generate toolpath</b> option does not recognize changes to the <b>Roll cutter around corners</b> setting in a Contour toolpath.	12/30/22
R-32042	TP4	<i>Milling Toolpaths</i>	Changing the program number of a 2D Dynamic operation generates a dirty toolpath.	12/30/22
R-30658	TP4	<i>Backplot/Verify/Simulation</i>	<b>Save to Defaults</b> does not save the <b>Label Display</b> settings.	12/30/22
D-50572	TP4	<i>Milling Toolpaths</i>	Waterline toolpath generates an incorrect cut order.	12/30/22
R-33112	TP4	<i>Backplot/Verify/Simulation</i>	Verify falsely triggers the <b>Proximity Alert</b> .	12/30/22
R-30295	TP4	<i>Selection/Chaining</i>	Stock Model does not default to solid body selection.	12/30/22
R-32491	TP4	<i>Backplot/Verify/Simulation</i>	After multiple simulations, Verify cuts with previous tools from previous operations instead of the displayed tool.	12/30/22
R-30094	TP4	<i>Milling Toolpaths</i>	Modifying the approximate start point of a duplicated Surface Finish operation removes it from the source operation.	12/30/22

Number	Release	Category	Description	Date
R-30831	TP4	<i>Milling Toolpaths</i>	Displaying the start point of a Dynamic OptiRough toolpath deletes other geometry.	12/30/22
R-32103	TP4	<i>Backplot/Verify/Simulation</i>	Simulator displays an incorrect tool orientation.	12/30/22
R-32026	TP4	<i>System</i>	The Multi-Threading Manager does not display on top of the main Mastercam window.	12/30/22
R-31965	TP4	<i>CAD</i>	An Overflow UV-generated surface does not break as expected when the projection intersects with an edge of the target surface.	12/30/22
R-26813	TP4	<i>Milling Toolpaths</i>	Dynamic Mill operations that combine <b>Avoidance regions</b> and <b>Incremental</b> machining depths, cut at the wrong depth.	12/30/22
R-32377	TP4	<i>Backplot/Verify/Simulation</i>	When simulating a Probing operation, the probe body does not display.	12/30/22
R-31998	TP4	<i>System</i>	In Levels Manager, the <b>Delete entities</b> command does not delete blanked entities.	12/8/22
R-32231	TP4	<i>Turning Toolpaths</i>	When Mill-Turn Verify is in <b>Length</b> mode, <b>Play</b> shows a false collision warning, but <b>Step</b> shows no warning.	12/8/22
R-32821 R-33051	TP4	<i>CAD</i>	The <b>Delete Duplicates</b> function should work as quickly as <b>Find Overlap</b> .	12/8/22
R-32458	TP4	<i>Turning Toolpaths</i>	In Mastercam Simulator, color looping does not work when you select the <b>Simulation</b> tab and deselect <b>Use Mastercam colors</b> in the simulator options.	12/8/22
R-31913	TP3	<i>Turning Toolpaths</i>	A custom 3D Lathe tool displays no insert.	11/22/22
R-23783	TP3	<i>Milling Toolpaths</i>	3D Chamfer is gouging a part.	11/22/22
R-16554	TP3	<i>Milling Toolpaths</i>	2D Dynamic Mill cuts stock on the back feed move.	11/22/22
R-32439 R-32639	TP2	<i>Milling Toolpaths</i>	2D Helix Bore that uses <b>Axis substitution</b> regenerates incorrectly.	11/10/22
R-32674	TP2	<i>Milling Toolpaths</i>	Surface Finish Contour violates the selected drive surfaces with <b>Detect undercuts</b> checked.	11/10/22
R-32427	TP2	<i>File Management</i>	The <b>File, Open</b> command crashes Mastercam and gives no message.	11/10/22
R-32563	TP2	<i>Milling Toolpaths</i>	The Hybrid toolpath is detecting no flats after regenerating the toolpath.	11/10/22
R-32085	TP2	<i>File Management</i>	When imported from SOLIDWORKS, STEP file, MBD data might not be clean.	10/20/22
D-49368	TP2	<i>Milling Toolpaths</i>	2D High Speed Area Mill crashes Mastercam when	10/31/22

Number	Release	Category	Description	Date
R-32369			regenerating with solid chains.	
R-32291	TP2	System	Unable to set the plane origin with AutoCursor.	10/20/22
R-31383	TP2	Milling Toolpaths	2D Contour Remachining is not producing a toolpath with stock to leave on walls.	10/20/22
R-31910	TP2	File Management	A SOLIDWORKS File is not opening in Mastercam 2023.	10/20/22
D-49390	TP2	File Management	Merging a DXF into a Mastercam file does not work well with bookmarked viewsheets.	10/20/22
R-23780	TP2	File Management	Saving as a STEP file is slow.	10/20/22
R-31697	TP2	System	The toolpath group name is not updated in the NCI after importing operations.	10/20/22
R-32271	TP2	System	The Plane Manager is blinking when the GView is set to a custom plane.	10/20/22
R-32029	TP2	File Management	A SOLIDWORKS assembly will not load in Mastercam 2023/2024.	10/20/22
S-98790	TP2	File Management	3D Annotations containing multiple call outs display incorrect data.	10/20/22
R-32565	TP2	Milling Toolpaths	A Stock Model using OptiRough, a custom plane, and a maximum arc radius of 15000.00 returns a solid block.	10/31/22
R-32368	TP2	File Management	The <b>Search sub-folders</b> option can cause Mastercam to crash.	10/20/22
R-32276	TP2	Milling Toolpaths	The 2D Contour toolpath fails at trimming with multi passes.	10/20/22
D-47834	TP1	CAD	The <b>Trim to Faces</b> option in Solid Extrude remains active even when not selected.	8/18/22
R-29968	TP1	Backplot/Verify /Simulation	Verify displays an error during a block drill operation.	8/18/22
R-09622	TP1	Milling Toolpaths	The <b>Delete</b> option in the right-click menu on the <b>Model Geometry</b> page of Dynamic OptiRough operations does not work correctly.	8/18/22
S-93708	TP1	Machine Systems	AutoComplete does not work in Code Expert after you save a file to a new format.	8/18/22
R-16278	TP1	Milling Toolpaths	Raster operations do not output the tool inspection code when <b>Perpendicular fill</b> is active.	8/18/22
R-30967	TP1	Milling Toolpaths	Gouging occurs during a linking move in a Restmill operation.	8/18/22



Number	Release	Category	Description	Date
R-14609	TP1	<i>Milling Toolpaths</i>	Area Roughing and Dynamic OptiRough operations that use rest material do not remove the expected material when tool collision is active.	8/18/22
R-29314	TP1	<i>Milling Toolpaths</i>	Contour with <b>Depth Cuts</b> causes problems with OptiRough.	8/18/22
S-95860	TP1	<i>CAD</i>	The <b>Create Geometry</b> option remains selected after you exit the <b>Note</b> function.	8/18/22
D-45320	TP1	<i>CAD</i>	Tangent dimensions do not always display a tangent result, depending on how far the selected arc extends.	8/18/22
R-27728	TP1	<i>Milling Toolpaths</i>	The entry motion for a Area Roughing operation gouges the part.	8/18/22
R-13609	TP1	<i>Milling Toolpaths</i>	The tool plunges instead of ramping down in an Area Roughing operation.	8/18/22
R-05611	TP1	<i>Milling Toolpaths</i>	An incorrect view matrix skews an Area Roughing operation.	8/18/22
R-11754	TP1	<i>Milling Toolpaths</i>	Pencil operation gouges the part when <b>Collision checking</b> is active.	8/18/22
R-29229	TP1	<i>Machine Systems</i>	The <code>API.MPPParam()</code> function does not return the tool grade.	8/18/22
D-15755	TP1	<i>Milling Toolpaths</i>	Rest Roughing operation gouges the part on an entry move.	8/18/22
R-30276	TP1	<i>Machine Systems</i>	The <code>MP.NET ToolDiameter</code> and <code>ToolRadius</code> tokens do not return an accurate value when you post Lathe drill operations.	8/18/22
R-13248	TP1	<i>Milling Toolpaths</i>	Area Roughing operation outputs excessive tool motion.	8/18/22
R-31118	TP1	<i>File Management</i>	Mastercam does not create edge curves on imported Parasolid surfaces.	8/18/22
R-18786	TP1	<i>Milling Toolpaths</i>	A Surface Finish Radial operation begins at the incorrect location.	8/18/22
R-30370	TP1	<i>Milling Toolpaths</i>	Rapid moves between passes consist of two moves instead of one during a Raster operation.	8/18/22
R-19191	TP1	<i>Milling Toolpaths</i>	The holder clearance value causes the toolpath to change incorrectly.	8/18/22
R-07021	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough incremental clearance is not applied consistently.	8/18/22
R-14118	TP1	<i>Backplot/Verify /Simulation</i>	Pencil operations do not generate when the operation uses a custom plane that is not near the world origin	8/18/22

Number	Release	Category	Description	Date
			coordinates.	
R-08297	TP1	Milling Toolpaths	An Area Roughing operation that uses a stock model incorrectly alters between climb and conventional cutting.	8/18/22
R-04647	TP1	Wire	Gouging occurs in a No Core wirepath when <b>Compensation type</b> is set to <b>Control</b> .	8/18/22
R-06668	TP1	Milling Toolpaths	A Waterline operation does not always respect the tool retract height.	8/18/22
D-48128	TP1	File Management	A 3D annotation displays incorrect tolerance data in an imported .sldprt file.	8/18/22
D-09009	TP1	Milling Toolpaths	The tool goes beyond the user-defined maximum Z depth in a Hybrid operation.	8/18/22
R-13762	TP1	Milling Toolpaths	Mastercam crashes when a user selects both solids for <b>Turn Profile</b> and then clicks <b>OK</b> .	8/18/22
R-06867	TP1	Milling Toolpaths	Changing the stepdown value incorrectly changes the horizontal lead-in motion of a Waterline toolpath.	8/18/22
D-47999	TP1	CAD	When the user creates dimensions, AutoCursor relative positions are defined by the view coordinate system rather than the world or system coordinates.	8/18/22
D-14537	TP1	Milling Toolpaths	A 2D Pocket operation generates random arc motion.	8/18/22
R-06188	TP1	Backplot/Verify /Simulation	Verify does not respect the sheet origin of nested wirepaths.	8/18/22
R-30516 R-30241	TP1	Milling Toolpaths	Unified Multiaxis - Parallel is missing data when mirrored.	8/18/22
R-29093	TP1	Milling Toolpaths	Helix Bore with no rough or finish passes displays no warning.	8/18/22
R-08573	TP1	Milling Toolpaths	Dynamic OptiRough is not using arcs on entry.	8/18/22
R-14196	TP1	Backplot/Verify /Simulation	3D high speed toolpaths do not dynamically update the <b>Skip pockets small than field</b> .	8/18/22
D-19726	TP1	Backplot/Verify /Simulation	Raster operation contains unnecessary retract motion.	8/18/22
R-15591	TP1	Milling Toolpaths	Area Roughing operation does not cut to the specified Z depth.	8/18/22
R-27708	TP1	Milling Toolpaths	OptiRough operations post a jumping motion in the Z direction when <b>Full Vertical Retract</b> is active.	8/18/22
R-29467	TP1	Machine Systems	The MP.NET ToolOrientationType token returns incorrect information.	8/18/22

Number	Release	Category	Description	Date
R-30508	TP1	CAD	Changes to visibility settings on the <b>Leaders / Witness</b> page of <b>System Configuration</b> revert after you create a dimension.	8/18/22
R-30512				
R-13180	TP1	System	Dynamic OptiRough toolpath generates while its parent operation is generating.	8/18/22
D-48395	TP1	Milling Toolpaths	Linear axes overrun their travel limits.	8/18/22
R-17437	TP1	Milling Toolpaths	A Waterline operation creates incorrect motion in a corner of the part.	8/18/22
R-15793	TP1	Milling Toolpaths	Stock Model using Contour ramp operations is processing too slowly.	8/18/22
R-27621	TP1	Milling Toolpaths	Area Roughing is gouging.	8/18/22
R-05161	TP1	Backplot/Verify /Simulation	3D High Speed milling operations incorrectly result in a visible pattern in Verify and on the part.	8/18/22
R-11423	TP1	Milling Toolpaths	A warning displays when a 3D High Speed operation uses a roughing tool that is smaller than the finishing tool for rest machining.	8/18/22
R-17762	TP1	Milling Toolpaths	Using the highfeed tool in Area Roughing, the operation does not cut to the wall.	8/18/22
R-31183	TP1	File Management	Saving this file as STEP crashes Mastercam.	8/18/22
D-48714	TP1	CAD	Notes that are on multiple planes on a solid cannot be extruded with a single operation.	8/18/22
R-17504	TP1	Milling Toolpaths	Creating a new tool and saving it as the default while creating a Waterline toolpath causes Mastercam to crash.	8/18/22
R-17444	TP1	Milling Toolpaths	A Waterline operation incorrectly changes the <b>Stepdown</b> value after you use <b>Edit projection</b> .	8/18/22
R-08380	TP1	Milling Toolpaths	A Hybrid toolpath does not completely cut the drive surface.	8/18/22
R-15275	TP1	Milling Toolpaths	An Area Roughing operation does not work correctly in Mastercam 2017 and later versions.	8/18/22
R-18187	TP1	Milling Toolpaths	Waterline operations retract the tool before the last cut occurs.	8/18/22
R-16050	TP1	Milling Toolpaths	Saving a part file causes an assert message to appear.	8/18/22
R-17725	TP1	Milling Toolpaths	The Waterline operation fails to regenerate after saving <b>Wall Stock</b> to the parameters-defaults file twice.	8/18/22
R-30970	TP1	CAD	2D Swept is using an incorrect view and is gouging geometry.	8/18/22

Number	Release	Category	Description	Date
R-28495	TP1	<i>Milling Toolpaths</i>	Mastercam incorrectly applies <b>Infinite look ahead</b> to a 2D Contour operation that has <b>Compensation type</b> set to <b>Off</b> .	8/18/22
R-17105	TP1	<i>Milling Toolpaths</i>	A Radial operation is noisy and gouges the part.	8/18/22
R-10096	TP1	<i>Milling Toolpaths</i>	Area Roughing operation does not cut the entire toolpath.	8/18/22
R-08243	TP1	<i>Milling Toolpaths</i>	An Area Roughing operation gouges the part when the retract <b>Type</b> is <b>Minimum Distance</b> .	8/18/22
R-27281	TP1	<i>Milling Toolpaths</i>	Waterline operations retract to the world WCS when <b>Collision checking</b> is active.	8/18/22
R-02764	TP1	<i>Turning Toolpaths</i>	Lathe Stock Model operations that include a Stock Advance operation display an incorrect stock model.	8/18/22
R-30770	TP1	<i>File Management</i>	A single quotation mark in a level name becomes an underscore when you save the Mastercam file as .DWG and reopen it.	8/18/22
R-30917	TP1	<i>Machine Systems</i>	The .PrefixInc MP.net command does not work correctly during incremental mode.	8/18/22
R-18364	TP1	<i>Milling Toolpaths</i>	Entry leads are not always applied to Area Roughing operations.	8/18/22
R-07306	TP1	<i>Milling Toolpaths</i>	Roughing operation does not completely machine the last of four equal pockets.	8/18/22
R-14636	TP1	<i>Milling Toolpaths</i>	Using overlap in Circle Mill toolpaths results in an invalid arc error when posting.	8/18/22
R-30223	TP1	<i>Milling Toolpaths</i>	Multisurface cuts the compensation faces incorrectly in Mastercam 2022 and 2023.	8/18/22
D-48758	TP1	<i>System</i>	You can create a Drafting note without a font type specified.	8/18/22
R-23850	TP1	<i>Milling Toolpaths</i>	Raster is machining outside of the tool containment boundary.	8/18/22
R-30143	TP1	<i>Backplot/Verify/Simulation</i>	Mill-Turn Simulation shows a false collision on the right spindle after a pickoff operation.	8/18/22
R-23428	TP1	<i>Milling Toolpaths</i>	OptiRough that uses collision checking is giving a computation error.	8/18/22
R-30012	TP1	<i>Backplot/Verify/Simulation</i>	Classic backplot shows the drill moving through the part. Also, the hole order is wrong.	8/18/22
R-29916 R-30325	TP1	<i>Milling Toolpaths</i>	Multiaxis ProDrill operations do not output axis control settings.	8/18/22

Number	Release	Category	Description	Date
R-30874	TP1	<i>Milling Toolpaths</i>	A cutoff point is not generated when Mill-Turn Pickoff-Cutoff strategies create the operations.	8/18/22
R-31217	TP1	<i>Turning Toolpaths</i>	Stock model does not show the Contour C-axis operations correctly.	8/18/22
R-15731	TP1	<i>Milling Toolpaths</i>	A Raster operation gouges the part when the retract Type is set to Minimum Distance.	8/18/22
R-29486	TP1	<i>Machine Systems</i>	There is no MP post variable that recognizes the Mastercam license type as retail or evaluation.	8/18/22
R-04721	TP1	<i>Milling Toolpaths</i>	Restmill toolpaths create different output motion when modifying the Steep/Shallow options.	8/18/22
R-04954	TP1	<i>Milling Toolpaths</i>	When using a minimum distance with Dynamic OptiRough, the retract feed rate is being used to cut through the stock model.	8/18/22
D-14130	TP1	<i>Milling Toolpaths</i>	Users have to right-click in the Toolpaths Manager to save a stock model to file.	8/18/22
R-30871	TP1	<i>CAD</i>	The Transform Move to Origin function incorrectly changes the solid attributes.	8/18/22
D-48563	TP1	<i>CAD</i>	The Reselect button in the Primitive Cylinder function panel does not function as expected.	8/18/22
R-14535	TP1	<i>Milling Toolpaths</i>	Waterline operations do not respect the Horizontal arc entry setting.	8/18/22
R-32101	TP1	<i>File Management</i>	When saving a Step file, rational NURB Splines export incorrectly.	9/8/22
R-04358	TP1	<i>System</i>	Arcs with a radius of 0 are being output to the NCI.	8/18/22
R-31354	TP1	<i>CAD</i>	You cannot create a vector from the center of the selected geometry when you click the Reselect button in the Translate panel.	8/18/22
R-06027	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough produces no motion.	8/18/22
R-14601	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is not cutting all surfaces when using a face mill tool.	8/18/22
R-29501	TP1	<i>Milling Toolpaths</i>	The cut order for a Raster toolpath is different than previous releases.	8/18/22
R-29184	TP1	<i>Machine Systems</i>	The longhand output for a Mill-Turn Peck Drill operation does not include the peck down move.	8/18/22
D-40504	TP1	<i>Milling Toolpaths</i>	Backfeed moves are gouging the material when using Dynamic OptiRough.	8/18/22
R-28939	TP1	<i>Milling Toolpaths</i>	2D Contour that uses a 3D chain is retracting too high.	8/18/22

Number	Release	Category	Description	Date
R-19043	TP1	<i>Milling Toolpaths</i>	The selection order of the containment boundaries affects the entry motion for Dynamic OptiRough.	8/18/22
R-29785	TP1	<i>Milling Toolpaths</i>	A stock model does not show the connecting feed move between depth passes with a 2D Contour toolpath.	8/18/22
D-06910	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough does step-up cuts where none are needed.	8/18/22
R-31110	TP1	<i>Milling Toolpaths</i>	The Multiaxis Unified toolpath is noisy compared to previous Mastercam versions.	8/18/22
R-31391	TP1	<i>File Management</i>	Clean operations become dirty when you open the part file.	8/18/22
R-19651	TP1	<i>Milling Toolpaths</i>	Area Roughing is cutting air.	8/18/22
R-17315	TP1	<i>Milling Toolpaths</i>	The <b>Transition</b> page parameters do not allow calculations when the user presses [Enter].	8/18/22
R-22183	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is ignoring stock to leave.	8/18/22
R-13319	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough with an unchecked <b>Steep/Shallow, Use Z depths</b> is not respecting the stock model as rest material.	8/18/22
R-04326	TP1	<i>Milling Toolpaths</i>	Area Roughing is machining finished walls when referencing the stock model, but not when referencing STL.	8/18/22
R-29960	TP1	<i>Milling Toolpaths</i>	Blend's finishing is not smooth and appears to be faceted.	8/18/22
R-30916	TP1	<i>System</i>	The File Explorer search field scales inconsistently on a 4K monitor.	8/18/22
R-23864	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough misses stock that is accessible.	8/18/22
R-10136	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is using an incorrect entry helix height.	8/18/22
R-23036	TP1	<i>Milling Toolpaths</i>	Area Roughing is plunging into the material.	8/18/22
R-31187	TP1	<i>Milling Toolpaths</i>	Unexpected plane-origin shift after changing a toolpath operation's planes.	8/18/22
R-09125	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough retract moves are incorrect.	8/18/22
R-17101	TP1	<i>Milling Toolpaths</i>	3D High Speed toolpaths using the <b>Tilt to avoid collision</b> checking method causes the linking feed moves to change to rapid moves.	8/18/22
R-30919	TP1	<i>Selection/Chaining</i>	In <b>Relative</b> mode, pressing [i] does not activate the intersection AutoCursor mode.	8/18/22

Number	Release	Category	Description	Date
R-19289	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is not collision checking the holder.	8/18/22
R-09714	TP1	<i>Milling Toolpaths</i>	The depth cuts value output for Dynamic OptiRough is incorrect.	8/18/22
R-14907 D-45137	TP1	<i>Backplot/Verify/Simulation</i>	Machine Simulation will not allow the user to use a 3-axis milling center.	9/22/22
R-31285	TP1	<i>File Management</i>	Parasolid level and solid names are not imported from this file.	8/18/22
R-09557	TP1	<i>Milling Toolpaths</i>	The OptiRough linking move is gouging the part.	8/18/22
R-15011	TP1	<i>Milling Toolpaths</i>	Images on the <b>Toolpath Type</b> page of Area Roughing and Dynamic OptiRough operations do not match the selected <b>Strategy</b> on the <b>Toolpath Control</b> page.	8/18/22
D-37118	TP1	<i>Milling Toolpaths</i>	The Raster toolpath is noisy.	8/18/22
R-27739	TP1	<i>Milling Toolpaths</i>	Waterline is generating extra cuts on floor surfaces.	8/18/22
D-48710	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough that uses collision checking is gouging the stock.	8/18/22
R-09042	TP1	<i>Milling Toolpaths</i>	Area Roughing, when using trochoidal motion and holder collision checking, the holder is clipping the clamp.	8/18/22
R-29607	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough with <b>Detect Undercut Stock</b> is not cutting all of the material correctly.	9/8/22
R-21816	TP1	<i>Milling Toolpaths</i>	OptiRough plunges into the material.	8/18/22
R-29482	TP1	<i>Milling Toolpaths</i>	Bad toolpath motion is created around a cylinder for a Multiaxis Unified toolpath.	8/18/22
R-23538	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough that uses collision checking is missing areas.	8/18/22
R-31353	TP1	<i>File Management</i>	The default machine does not load in imported .SLDPRT files with no Mastercam for SOLIDWORKS data.	8/18/22
R-16737	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is taking a full width cut.	8/18/22
R-31295	TP1	<i>CAD</i>	The MRU data fields in the <b>Transform Translate</b> panel are not updating correctly.	8/18/22
R-10881	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is cutting identical geometry differently.	8/18/22
R-10455	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough gouges upon entry with a horizontal arc entry lead in.	8/18/22
R-31445	TP1	<i>Milling Toolpaths</i>	Mastercam displays an error for a Stock Model that is	8/18/22

Number	Release	Category	Description	Date
R-31597			using a source operation with a Slot Mill cutter and with the <b>Mill flutes only</b> option unchecked.	
D-07692	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is gouging.	8/18/22
R-19455	TP1	<i>Milling Toolpaths</i>	Waterline's transition moves produce odd results when using a ramp entry with small angles.	8/18/22
D-49127	TP1	<i>File Management</i>	Mastercam does not apply the resolution tolerance to curve linearization when you export a file to OBJ.	8/18/22
R-31417	TP1	<i>File Management</i>	Mastercam creates incorrect cutter information when you import a custom form cutting tool from DXF.	8/18/22
R-16637	TP1	<i>Backplot/Verify/Simulation</i>	Classic machine simulation is reporting a false error.	8/18/22
D-15207	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is ignoring the Z clearance value on the <b>Transitions</b> page.	8/18/22
D-14523	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough using a stock model yields incomplete results.	8/18/22
R-13648	TP1	<i>Milling Toolpaths</i>	A Raster operation does not respect the containment boundary.	8/18/22
D-16859	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough operations are marked dirty when clicking OK in the toolpath dialog box with unchanged parameters.	8/18/22
R-24222	TP1	<i>Milling Toolpaths</i>	Waterline is regenerating legacy files incorrectly.	8/18/22
R-31317	TP1	<i>Milling Toolpaths</i>	Mill-Turn Transform is not supporting the multiaxis path when set to 3- or 4-axis output.	8/18/22
R-19297	TP1	<i>Milling Toolpaths</i>	When retracting, the leftover stock and flute make contact.	8/18/22
R-30562	TP1	<i>Backplot/Verify /Simulation</i>	Mill-Turn Simulation shows a false collision between the stock and jaws during a part transfer.	8/18/22
R-08109	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough does not take all of the stock model into account.	8/18/22
R-31589	TP1	<i>File Management</i>	Duplicate lines are being created when saving dimensions as AutoCAD DWG/DXF.	8/18/22
R-20500	TP1	<i>Milling Toolpaths</i>	A Waterline toolpath with <b>Tilt to avoid</b> selected is violating geometry.	8/18/22
R-13578	TP1	<i>Milling Toolpaths</i>	A Waterline operation gouges the part when the retract <b>Type</b> is set to <b>Minimum Distance</b> .	8/18/22
R-04122	TP1	<i>Machine Systems</i>	Subprograms do not work due to problems with the NCI lines 1018 and 1019.	8/18/22
R-30205	TP1	<i>Milling Toolpaths</i>	Stock Model that uses a C-axis face operation is	8/18/22




Number	Release	Category	Description	Date
			incorrect.	
R-21195	TP1	<i>Milling Toolpaths</i>	Settings in the <b>Model Geometry</b> page are changing another operation's <b>Model Geometry</b> page.	8/18/22
R-21683	TP1	<i>Milling Toolpaths</i>	Raster ignores <b>Stock to leave</b> on machining geometry when using <b>Tool contact point</b> .	8/18/22
D-49473	TP1	<i>File Management</i>	Mastercam 2023/2024 importers lose the color information when merging coincident topology.	9/8/22
D-49097	TP1	<i>File Management</i>	Inventor 2023 files are not supported in Mastercam 2023/2024.	8/18/22
R-15916	TP1	<i>Milling Toolpaths</i>	Dynamic OptiRough is starting from the inside when told to start from the outside.	8/18/22
R-31027	TP1	<i>Milling Toolpaths</i>	Multiaxis Pocket parameter error.	8/18/22
R-30480	TP1	<i>File Management</i>	Unigraphics/NX file will not import into Mastercam 2022/2023.	8/18/22
R-31604	TP1	<i>Toolpath Utility</i>	A copied Transform operation does not regenerate when source is set to NCI.	8/18/22
R-31324	TP1	<i>CAD</i>	Planes - There is a section view issue with mesh entities.	8/18/22
R-18342	TP1	<i>File Management</i>	Verify <b>Stock to leave</b> values lost when saving a file.	8/18/22
R-30496	TP1	<i>Milling Toolpaths</i>	A 2D Dynamic Mill operation does not produce a toolpath when certain geometry types are selected.	8/18/22
R-31901	TP1	<i>System</i>	The status area for the Cplane, Tplane, and WCS works improperly.	9/8/22
R-31569 R-29872	TP1	<i>Milling Toolpaths</i>	Spindle speed is not output if it matches the tool for Advanced Drill.	8/18/22
R-31567 R-29352	TP1	<i>Milling Toolpaths</i>	Multiaxis Curve creates a move on the tool axis control surface, not the compensation surface.	8/18/22
R-30801	TP1	<i>File Management</i>	No 3D annotations are imported from this Inventor assembly.	8/18/22
R-30061	TP1	<i>Milling Toolpaths</i>	3D Blend with <b>Project</b> set to <b>2D</b> and with a tight stepover does not output the entire toolpath.	9/8/22
R-31592	TP1	<i>Toolpath Utility</i>	Toolpath Backplot/Verify/Simulationtransform flips some arc moves.	8/18/22
R-31514 R-31540	TP1	<i>File Management</i>	Mastercam generates an error when extracting an mcam-content file.	8/18/22

Number	Release	Category	Description	Date
R-23850	TP1	<i>Milling Toolpaths</i>	Raster is machining outside of the tool containment boundary.	8/18/22
R-31499	TP1	<i>Backplot/Verify/Simulation</i>	The spindle does not stop when the spindle speed is set to 0 in a Mill-Turn Simulation.	8/18/22
R-31162 R-30790	TP1	<i>Milling Toolpaths</i>	The tool ignores the tool axis control lines for Multiaxis Curve.	8/18/22
R-31032	TP1	<i>File Management</i>	Mastercam does not import all of the solids from Inventor.	8/18/22
R-26801	TP1	<i>Milling Toolpaths</i>	Waterline rest passes are incorrect when referencing the stock model.	8/18/22
R-26796 D-45253	TP1	<i>Wire</i>	Mastercam does not remove chips in verify when the wire thickness is less than .28mm.	9/29/22
R-09404	TP1	<i>Backplot/Verify/Simulation</i>	Verify does not display the corner radius for a Face Mill toolpath.	9/29/22
R-32226 R-31304	TP1	<i>File Management</i>	Mastercam crashes when saving a part as an IGES file.	9/29/22
R-30595 D-48445	TP1	<i>Milling Toolpaths</i>	2D Facing does not respect the override spindle speed when <b>Keep tool down</b> is checked.	9/29/22
R-32207	TP1	<i>Milling Toolpaths</i>	High Speed Toolpath linking applies secondary leads when the <b>Secondary leads</b> checkbox is not selected.	9/29/22
R-31269	TP1	<i>Milling Toolpaths</i>	Area Rest Roughing with an arc move gouges the part.	9/29/22
R-32193 R-32177	TP1	<i>CAD</i>	Mastercam crashes when the user presses [Esc] while in an <b>Analyze Entity Properties</b> dialog box with the focus set to <b>Color</b> or <b>Levels</b> .	9/29/22
R-31028	TP1	<i>File Management</i>	There is an assert in MachineDefMgr when exporting a file to XML.	9/29/22



**Attention! Updates may be available.  
Please refer to [my.mastercam.com/product-downloads](http://my.mastercam.com/product-downloads) for the latest downloads.**



**CNC Software, LLC**  
671 Old Post Road  
Tolland, CT 06084 USA

  
[www.mastercam.com](http://www.mastercam.com)



Mastercam® is a registered trademark of CNC Software, LLC. All other trademarks are property of their respective owners.  
©1983-2022. All rights reserved.