

17 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 5.2mm
GAP = Millinglot: 1/8 "or 3.35 mm

16 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.4 mm
GAP = Millinglot: 1/8 "or 3.175 mm

15 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
GAP = Millinglot: 1/8 "or 3.175 mm

14 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.8 mm
Millinglot: 1/8 "or 3.175 mm

13 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
Millinglot: 1/8 "or 3.175 mm

12 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
Millinglot: 1/8 "or 3.175 mm

11 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.8 mm
Millinglot: 1/8 "or 3.175 mm

10 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 10 mm
Millinglot: 1/8 "or 3.175 mm

9 PINE - PLYWOOD - 15 mm
Smallest Wood Connection =9 mm
GAP 6,35 mm (Millinglot: 1/8 "or 3.175 mm)



8 PINE - PLYWOOD - 15 mm
Smallest Wood Connection =5.3mm
GAP 6,35 mm (Millinglot: 1/8 "or 3.175 mm)

7 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 4mm
Millinglot: 1/8 "or 3.175 mm

6 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 8.2mm
Millinglot: 1/8 "or 3.175 mm

5 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 8mm
GAP = 10 mm (Millinglot: 1/8 "or 3.175 mm)

4 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 4.5mm
GAP = Millinglot: 1/8 "or 3.175 mm

3 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 7mm
GAP = Millinglot: 1/8 "or 3.175 mm

2 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.5mm
Millinglot: 1/8 "or 3.175 mm

1 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 5mm
Millinglot: 1/8 "or 3.175 mm



17 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 5.2 mm
GAP = Millinglot: 1/8 "or 3.175 mm

16 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.4 mm
GAP = Millinglot: 1/8 "or 3.175 mm

15 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
GAP = Millinglot: 1/8 "or 3.175 mm

14 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.8 mm
Millinglot: 1/8 "or 3.175 mm

13 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
Millinglot: 1/8 "or 3.175 mm

12 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3 mm
GAP = Millinglot: 1/8 "or 3.175 mm

11 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.8 mm
Millinglot: 1/8 "or 3.175 mm

10 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 10 mm
Millinglot: 1/8 "or 3.175 mm

9 PINE - PLYWOOD - 15 mm
Smallest Wood Connection =9 mm
GAP 6,35 mm (Millinglot: 1/8 "or 3.175 mm)

8 PINE - PLYWOOD - 15 mm
Smallest Wood Connection =5.3mm
GAP 6,35 mm (Millinglot: 1/8 "or 3.175 mm)

7 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 4mm
Millinglot: 1/8 "or 3.175 mm

6 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 8.2mm
Millinglot: 1/8 "or 3.175 mm

5 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 8mm
GAP = 10 mm (Millinglot: 1/8 "or 3.175 mm)

4 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 4.5mm
GAP = Millinglot: 1/8 "or 3.175 mm

3 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 7mm
GAP = Millinglot: 1/8 "or 3.175 mm

2 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 3.5mm
Millinglot: 1/8 "or 3.175 mm

1 PINE - PLYWOOD - 15 mm
Smallest Wood Connection = 5mm
Millinglot: 1/8 "or 3.175 mm